

17 July 2017

via FedEx

**URGENT FIELD SAFETY NOTICE
MEDICAL DEVICE FIELD CORRECTION**

**Maquet/Datascope CS100i Intra-Aortic Balloon Pump (IABP)
Maquet/Datascope CS100 Intra-Aortic Balloon Pump (IABP)
Maquet/Datascope CS300 Intra-Aortic Balloon Pump (IABP)**

AFFECTED PRODUCT	PART NUMBER	DISTRIBUTION DATE
<p style="text-align: center;">CS100i IABP CS100 IABP CS300 IABP</p>	<p style="text-align: center;">0998-UC-0446HXX; 0998-UC-0479HXX 0998-00-3013-XX; 0998-UC-3013-XX 0998-00-3023-XX; 0998-UC-3023-XX</p>	<p style="text-align: center;">March 24 2003 through June 16 2017</p>

PLEASE FORWARD THIS INFORMATION TO ALL CURRENT AND POTENTIAL CS100/CS100i AND CS300 INTRA-AORTIC BALLOON PUMP (IABP) USERS WITHIN YOUR INSTITUTION.

Dear Risk Manager,

This Urgent Medical Device Field Correction involves two issues presented below and on the following page, that could result in an interruption and/or delay in therapy to the patient prior to and/or during use of your CS100/CS100i or CS300 IABP. This field correction also applies to any System 98 or System 98XT IABP which was converted to a CS100i or CS300 IABP.

Identification of the Issues:

Maquet/Getinge has received complaints involving the CS100/CS100i and CS300 IABPs regarding the following issues:

- False blood detection alarm, and
- The ingress of fluids into the IABP affecting various electronic circuit boards.

Either issue could potentially prevent initiation or continuation of therapy. This Field Corrective Action addresses both issues.

Maquet/Getinge would like to inform our customers affected by the field corrections that the risk-benefit of using an affected CS100/CS100i or CS300 IABP should be assessed by your medical team for each patient, when no alternative IABP or alternative therapy is available.

Blood Detection Alarm:

The optical blood detection circuit is activated for the entire autofill process and is triggered by an 8 millisecond interruption of the light path in the circuit. If this blood detection circuit is triggered, the IABP stops the autofill process and generates a Blood Detected high priority alarm. The Blood Detected Help Screen instructs the operator to check for blood in the catheter and if none is found, turn the IABP off, wait ten seconds, turn the power on and press the START key to refill the IAB and resume therapy. This alarm can only be cleared by manually powering off and then turning on the IABP.

Maquet/Getinge has determined that condensation in the Drain Line tubing may lead to a false Blood Detection alarm activating when no blood is present. While the CS100/CS100i and CS300 Operating Instructions provide clear corrective actions if this alarm sounds, Maquet/Getinge has developed software to mitigate the potential for “false” blood detection alarms. This will require a hardware change performed by a service representative to the CS100/CS100i and CS300 IABPs.

Fluid Ingression

IABPs are electro mechanical systems with various electronic circuit boards for control of the therapy. Liquid spills, such as saline, can create bridges of resistance between the circuit components; causing the circuit not to function as intended. This can impact initiation or continuation of therapy. It is important to note that the instructions for use contain the warning to *“Never place fluids on top of the unit. Make sure that the saline container and tubing do not hang directly over the IABP. In case of accidental spillage, wipe clean immediately and have the unit serviced to ensure no hazard exists”*. In the event of fluid spills, Maquet/Getinge has evaluated the potential entry points and created a gasket kit that seals these ingress points. This field action will require a service representative to install the gaskets in the IABP.

General Information and Overall Action for User:

Patients receiving IABP therapy are in critical condition and sudden interruption of therapy could result in unsafe, hemodynamic instability. Please adhere to the following instructions when using an affected CS100/CS100i or CS300 IABP:

- 1) Pursuant to the WARNINGS section of our CS100/CS100i or CS300 IABP Operating/User Instructions, clinicians are instructed not to leave the patient unattended during IABP therapy.
- 2) An additional hazard associated with a sudden shutdown is related to the static condition (no inflating or deflating) of the balloon during the interruption of therapy. It is important to note the following WARNING in the CS100/CS100i or CS300 IABP Operating Instructions Manual:

WARNING: The patient balloon should not remain inactive in the patient (i.e., not inflating or deflating) for more than 30 minutes, due to the potential for thrombus formation.

In the unlikely event that a sudden interruption of therapy occurs, transfer the patient to an alternative IABP. The Intra-Aortic Balloon (IAB) Catheter Instructions for Use reiterates that a catheter should not remain inactive for more than 30 minutes, due to the potential for thrombus formation. If an alternative IABP is unavailable; manually inflate the IAB with air or helium and immediately aspirate, repeat every 5 minutes until either an alternate IABP is available or alternatively, the IAB Catheter should be removed from the patient. Please refer to the intra-aortic balloon catheter instructions for use, Manually Inflating and Deflating a Catheter. The patient should be treated according to your facility's treatment protocols and caregivers' clinical judgment to ensure hemodynamic stability.

- 3) For Blood Detection Alarm - Until the service is performed, we recommend following the Blood Detection Alarm Help Screen found in the operating instruction to validate or clear the alarms. We also recommend reviewing the water condensation procedure (CS100/CS100i and CS300 Operating Instructions section 3.4.1) to reduce the potential for condensation accumulation. In the event the IABP fails to successfully cycle and clear the alarm, remove the IABP from service and contact your local Maquet/Getinge Sales & Service Office.
- 4) For Fluid Ingression - Until the service is performed, we recommend a review of the CS100/CS100i and CS300 Operating instructions regarding cautions on placement of fluids and hanging of bags of fluid over the IABP.
“Never place fluids on top of the unit. Make sure that the saline container and tubing do not hang directly over the IABP. In case of accidental spillage, wipe clean immediately and have the unit serviced to ensure no hazard exists”

Corrective Action:

Your facility will be contacted by a representative of the Maquet/Getinge Service Team to schedule on-site service of your CS100/CS100i or CS300 IABP.

Please complete the attached Medical Device Field Correction Response Form on page 5 to acknowledge that you have received this Medical Device Field Correction letter. Please return the completed form to your local Maquet/Getinge office. If you are a distributor who has shipped any affected products to customers, please forward this document to their attention for appropriate action.

Maquet/Getinge Group apologizes for any inconvenience you may experience as a result of this field correction. If you have any questions, please contact your local Maquet/Getinge representative.

Thank you for your cooperation and immediate assistance.

Sincerely,



Karen LeFevere

Director Regulatory Affairs and Quality Compliance Field Actions

17 July 2017

MEDICAL DEVICE FIELD CORRECTION RESPONSE FORM
 Please return the completed form to your local Maquet/Getinge office

Maquet/Datascope CS100i Intra-Aortic Balloon Pump (IABP)
Maquet/Datascope CS100 Intra-Aortic Balloon Pump (IABP)
Maquet/Datascope CS300 Intra-Aortic Balloon Pump (IABP)

AFFECTED PRODUCT	PART NUMBER	DISTRIBUTION DATE
CS100i IABP CS100 IABP CS300 IABP	0998-UC-0446HXX; 0998-UC-0479HXX 0998-00-3013-XX; 0998-UC-3013-XX 0998-00-3023-XX; 0998-UC-3023-XX	March 24 2003 through June 16 2017

[ENTER FACILITY NAME ADDRESS]

I acknowledge that I have reviewed and understand the 17 July 2017 Medical Device Field Correction Update Letter for the affected CS100/CS100i & CS300 Intra-Aortic Balloon Pump(s) at this facility.

I confirm that all users of the CS100/CS100i and CS300 Intra-Aortic Balloon Pump(s) at this facility have been notified accordingly.

Facility Representative:

Signature: _____ Date: _____

Name: _____ Phone: _____

Title: _____ Department: _____

Facility Name: _____

Address, City and Country: _____

Please return the completed form to your local Maquet/Getinge office