

### **URGENT FIELD SAFETY NOTICE: RA2021-2744351**

**ACTION REQUIRED** 

## **UPDATE**

October, 2021

#### **Identification of the Affected Product:**

Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral Trials
Refer to Attachment A, "PFA 2744351 Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral Trials," and **Attachment B, "Scope Expansion** PFA 2744351 Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral
Trials" for affected catalog and lot numbers.

Dear Customer,

Stryker has expanded the scope of a voluntary, lot-specific recall that was initiated on July 7, 2021, for the Restoris® MCK Femoral Trial and Patellofemoral Trials. The specific lot numbers that are impacted by the recall are included in **Attachment A** and **Attachment B** to this letter.

The purpose of this update letter is to notify new customers that are now in scope due to the scope expansion and to notify customers that received the initial recall letter in July 2021, that this recall has been expanded to include additional lots of the Restoris® MCK Femoral and Patellofemoral Trials.

Stryker has initiated a voluntary, lot number specific recall for:

- Restoris® MCK Femoral Trial, sizes 1 through 8 and 11 through 18 (LM/RL and RM/LL), of 16 catalog numbers (170501- 170508) and (170511–170518).
- **Restoris® MCK Patellofemoral Trial**, sizes 2 through 8 and 12 through 18 (Left and Right), of 14 catalog numbers (170402 170408) and (170412 170418).

The intent of this letter is to list hazards and harms potentially associated with the referenced products listed in **Attachment A**, "PFA 2682873 Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral Trials," and **Attachment B**, "**Scope Expansion** PFA 2682873 Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral Trials," and list any risk mitigation factors.

#### **Description of issue:**

Stryker has discovered that there is a potential that the threads on the Femoral Trial Slaphammer may not engage with the threads of the Restoris® MCK Femoral Trial(s) and/or Restoris® MCK Patellofemoral Trial(s), (collectively, "Trial(s)"), preventing the extraction of such Trials using the slaphammer after use. This is due to an undersized diameter of the non-threaded portion of the Trial's extraction hole, which may prevent the Femoral Trial Slaphammer from completely engaging.





As a result of this discrepancy, customers are instructed to confirm that the threads of Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) are able to fully engage with their Femoral Trial Slaphammer(s) at the site prior to use. Quarantine and discontinue use of the Trials identified in the affected product list that do not fully engage with the Femoral Trial Slaphammer and return the devices back to Stryker.

The Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) continue to meet their intended use of assessing the final fit and function of the femoral and patellofemoral implant prior to implantation.

Figure 1 below displays a Femoral Trial Slaphammer engaging with a Trial (conforming extraction hole) in the image at left, and a Femoral Trial Slaphammer that does not engage with the Trial in the image at right.

Figure 1:





Stryker is aware of complaints associated with the issue. There have been no reports of serious injuries due to the failure mode associated with this recall.

#### **Potential Hazards:**

• Failure to assemble the Restoris® MCK Femoral and Restoris® MCK Patellofemoral Trial with the Femoral Trial Slaphammer.

#### **Potential Harms:**

There are no harms associated with the potential hazard identified above.

#### **Risk Mitigations:**

If the surgeon is unable to assemble the Femoral Trial Slaphammer with a Restoris® MCK Femoral or Patellofemoral Trial(s) for extraction, the surgeon can use an alternative surgical instrument (or similar device) to remove the Trial(s).

#### **Required customer actions:**

Our records indicate that you have received at least one of the subject devices and you are therefore affected by this action.

We request that you read this notice carefully and complete the following actions:

1. Please inform users of this Urgent Field Safety Notice Update and forward this notice to all individuals who need to be made aware.



- 2. Immediately check all stock areas and/or operating room storage to determine if any devices from the affected product list are at your facility. See **Attachment B: "Scope Expansion** PFA 2744351 Restoris" MCK Femoral Trial and Restoris MCK Patellofemoral Trials."
- 3. Inspect all Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) to ensure that its threaded extraction hole(s) engages with any available Femoral Trial Slaphammers at your site.
- 4. <u>Discontinue use</u> of the recalled trial devices identified in **Attachment B: "Scope Expansion** PFA 2744351 Restoris" MCK Femoral Trial and Restoris MCK Patellofemoral Trials" which do not engage with your Femoral Trial Slaphammer(s) and return the Restoris MCK Femoral Trial(s) and Restoris MCK Patellofemoral Trial(s) devices to Stryker.
- 5. <u>Continue to use</u> the Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s)if the threads fully engage with the threads on the Femoral Trial Slaphammer.
- 6. Inform Stryker if any of the subject devices have been distributed to other organizations.
  - a. Please provide contact details so that Stryker can inform the recipients appropriately.
  - b. If you are a Distributor, note that you are responsible for notifying your affected customers.
- 7. Please inform Stryker of any adverse events concerning the use of the subject devices.
  - a. Please comply with any local laws or regulations concerning the notification of adverse events to your National Competent Authority.
- 8. Complete the attached customer response form. It may be that you no longer have any physical inventory on site. Completing this form will allow us to update our records and will also negate the need for us to send any further unnecessary communications on this matter. Therefore, please complete even if you no longer have any of the subject devices in your physical inventory.
- 9. Return the completed form to your nominated Stryker Representative (indicated below) for this PFA
  - a. On receipt of the form, a Stryker Representative will contact you to organize any applicable ongoing actions.

We request that you respond to this notice within 7 calendar days from the date of receipt.

Your designated contact person for this action is given below. Should you have any queries concerning this matter please do not hesitate to contact them directly.

Name:

Position:

E-mail:

Phone:

In line with the recommendations of the Meddev Vigilance Guidance document Ref.2.12-1, we can confirm that this FSCA has been notified appropriately to the National Competent Authority for your country.



On behalf of Stryker we thank you sincerely for your help and regret any inconvenience that may be caused. We would like to reassure you that Stryker is committed to ensuring that only conforming devices, meeting our high internal quality standards and your expectations, remain on the market.

Sincerely,

# Stryker URGENT FIELD SAFETY NOTICE: RA2021-2744351 **BUSINESS REPLY FORM**

| October 2021                                   |  |                    |                        |                 |
|--|--|--------------------|------------------------|-----------------|
| Product Name:                                  | Restoris ®MCK Femoral Tria   | al and Restoris ®M | CK Patellofemoral Tria | l               |
| Catalog and Lot#:                              | Refer to Attachment: PFA 27  | 44351              |                        |                 |
|  | <b>Field Safety Notice</b> letter frove referenced affected produc |                    | ctober 2021 informatio | on on the       |
| I have inspected the Restowithin my inventory. | oris ®MCK Femoral Trial an   | nd/ or the Restori | s ®MCK Patellofemor    | al Trial produc |
| Hospital/Agent/Risk Rep o                      | r Stryker Branch Rep Name  |                    |                        |                 |
| Hospital or Stryker Branch                     | Name   |                    | Date                   |                 |
| Hospital or Stryker Branch                     | Address/ City/State/ Postal (                                      | Code               |                        |                 |
| Hospital/Agent/Risk Rep o                      | r Stryker Branch Rep   |                    |                        |                 |
| (Signature)                                    |  |                    |                        |                 |
| PLEASE COMPLETE THIS I                         | FORM WITHIN 5 BUSINESS I   | DAYS AND RETUR     | N IT BY USING THE EN   | MAIL OR FAX     |
| Fax: xxxx or email to xxxx                     |  |                    |                        |                 |



#### Attachment: PFA 2744351 Restoris ®MCK Femoral Trial and Restoris® MCK Patellofemoral Trial

| Catalog # | GTIN#        | Lot# | Catalog # | GTIN #       | Lot# | Catalog # | GTIN #       | Lot# | Catalog # | GTIN#        | Lot# | Catalog # | GTIN #       | Lot# |
|-----------|--------------|------|-----------|--------------|------|-----------|--------------|------|-----------|--------------|------|-----------|--------------|------|
| 170402    | 848486003319 | 1N3G | 170415    | 848486003425 | 1QGP | 170501    | 848486003463 | 18QP | 170507    | 848486003524 | 12HN | 170515    | 848486003586 | 16W3 |
| 170402    |              | 1BM0 | 170415    |              | 1L8N | 170502    | 848486003470 | 11HG | 170507    |              | 12HM | 170515    |              | 16W4 |
| 170402    |              | 18QN | 170415    |              | 1CYD | 170502    |              | 11HH | 170507    |              | 15XY | 170515    |              | 16W1 |
| 170402    |              | 18QM | 170415    |              | 14X9 | 170502    |              | 11HE | 170507    |              | 15Y0 | 170515    |              | 16W2 |
| 170402    |              | 182Y | 170415    |              | 13BJ | 170502    |              | 1GX7 | 170507    |              | 15Y1 | 170515    |              | 1EAV |
| 170402    |              | 1830 | 170416    | 848486003432 | 2JP4 | 170502    |              | 22PG | 170507    |              | 1N32 | 170515    |              | 1GLM |
| 170403    | 848486003326 | 2JNE | 170416    |              | 1WWJ | 170502    |              | 23L4 | 170507    |              | 1N31 | 170515    |              | 1HNW |
| 170403    |              | 1WWG | 170416    |              | 1WWL | 170502    |              | 23L5 | 170507    |              | 1N30 | 170515    |              | 1HNV |
| 170403    |              | 15XV | 170416    |              | 1GX2 | 170502    |              | 22PE | 170507    |              | 1NN6 | 170515    |              | 38P8 |
| 170403    |              | 11HN | 170416    |              | 1GX3 | 170503    | 848486003487 | 14X5 | 170507    |              | 1NN5 | 170516    | 848486003593 | 14BP |
| 170404    | 848486003333 | 2JNM | 170417    | 848486003449 | 20V9 | 170503    |              | 16W8 | 170507    |              | 1NN8 | 170516    |              | 17CB |
| 170404    |              | 1WWH | 170417    |              | 1V0E | 170503    |              | 182X | 170508    | 848486003531 | 11AC | 170516    |              | 1AE1 |
| 170405    | 848486003340 | 1Q0V | 170417    |              | 1M26 | 170503    |              | 1G3X | 170508    |              | 16VN | 170516    |              | 1B0A |
| 170405    |              | 1BLM | 170417    |              | 1CYB | 170503    |              | 1G3W | 170508    |              | 1CY9 | 170516    |              | 1AE2 |
| 170405    |              | 1BLL | 170417    |              | 1ADJ | 170503    |              | 2R0D | 170508    |              | 1M21 | 170516    |              | 1B09 |
| 170405    |              | 17C3 | 170418    | 848486003456 | 32E3 | 170503    |              | 2JPV | 170508    |              | 1QGN | 170516    |              | 1CYA |
| 170405    |              | 17C4 | 170418    |              | 2Q3G | 170503    |              | 2R0E | 170508    |              | 1WWM | 170516    |              | 1MGD |
| 170405    |              | 11HW | 170418    |              | 2Q3H | 170503    |              | 38J6 | 170508    |              | 24X3 | 170516    |              | 1MGC |
| 170406    | 848486003357 | 17C9 | 170418    |              | 2DPG | 170503    |              | 38J8 | 170508    |              | 288E | 170516    |              | 1MGB |
| 170407    | 848486003364 | 1Q0Q | 170418    |              | 1YW7 | 170503    |              | 38J7 | 170508    |              | 288G | 170516    |              | 22PD |
| 170407    |              | 1Q0R | 170418    |              | 1BLR | 170504    | 848486003494 | 17BX | 170508    |              | 2XP1 | 170517    | 848486003609 | 12HD |
| 170408    | 848486003371 | 2Q3D | 170418    |              | 1ADM | 170504    |              | 1R5X | 170508    |              | 2XNX | 170517    |              | 15Y2 |
| 170408    |              | 2JPA | 170418    |              | 17CA | 170504    |              | 1QGR | 170511    | 848486003548 | 1PAP | 170517    |              | 15Y3 |
| 170408    |              | 2D2V |           |              |      | 170504    |              | 1R5W | 170511    |              | 1NNN | 170517    |              | 19A7 |
| 170408    |              | 1VQE |           |              |      | 170505    | 848486003500 | 11AG | 170512    | 848486003555 | 11A7 | 170517    |              | 19A8 |
| 170408    |              | 1Q0W |           |              |      | 170505    |              | 11AE | 170512    |              | 11J3 | 170517    |              | 1C1Q |
| 170408    |              | 1HNG |           |              |      | 170505    |              | 11AD | 170512    |              | 11J2 | 170517    |              | 1GLB |
| 170408    |              | 199M |           |              |      | 170505    |              | 1835 | 170512    |              | 20RV | 170517    |              | 1GLC |
| 170408    |              | 1B07 |           |              |      | 170505    |              | 19A0 | 170512    |              | 20RR | 170517    |              | 2A2H |
| 170412    | 848486003395 | 1W74 |           |              |      | 170505    |              | 1968 | 170513    | 848486003562 | 1V09 | 170517    |              | 2A2J |
| 170412    |              | 1CYC |           |              |      | 170505    |              | 1AE7 | 170513    |              | 1V0A | 170517    |              | 2JQC |
| 170412    |              | 15XN |           |              |      | 170505    |              | 1CCQ | 170513    |              | 227B | 170518    | 848486003616 | 1EAX |
| 170412    |              | 11HX |           |              |      | 170505    |              | 1CCN | 170513    |              | 20V6 | 170518    |              | 1EBO |
| 170412    |              | 11HY |           |              |      | 170505    |              | 1CCP | 170514    | 848486003579 | 11A1 | 170518    |              | 1EAY |
| 170413    | 848486003401 | 1MG3 |           |              |      | 170506    | 848486003517 | 14BM | 170514    |              | 1964 | 170518    |              | 1MG8 |
| 170413    |              | 1G40 |           |              |      | 170506    |              | 18R5 | 170514    |              | 1963 | 170518    |              | 1M20 |
| 170413    |              | 1GLN |           |              |      | 170506    |              | 1837 | 170514    |              | 1L8Q | 170518    |              | 1L8D |
| 170414    | 848486003418 | 246P |           |              |      | 170506    |              | 18R4 | 170514    |              | 1L8P | 170518    |              | 1MG7 |
|           |              |      |           |              |      | 170506    |              | 1GXJ | 170514    |              | 21H2 | 170518    |              | 1MG6 |
|           |              |      |           |              |      | 170506    |              | 1GXL | 170514    |              | 21H3 | 170518    |              | 1M1Y |
|           |              |      |           |              |      | 170506    |              | 1JRL | 170514    |              | 23L3 |           |              |      |
|           |              |      |           |              |      |           |              |      | 170514    |              | 23L2 |           |              |      |
|           |              |      |           |              |      |           |              |      |           |              |      |           |              |      |



#### <u>Attachment B: Scope Expansion</u> PFA 2744351 Restoris® MCK Femoral Trial and Patellofemoral Trials

| Catalag # | GTIN#        | Lot # | Catalag # | GTIN#        | Lot # | Catalag # | GTIN#        | Lot# | Catalag # | GTIN#        | Lot # |
|-----------|--------------|-------|-----------|--------------|-------|-----------|--------------|------|-----------|--------------|-------|
| 170402    | 848486003319 | 1073  | 110415    | 848486003425 | OVGA  | 170502    | 848486003470 | OXR3 | 170512    | 848486003555 | OXQY  |
| 170403    | 848486003326 | OYBM  | 110416    | 848486003432 | OR72  | 170502    |              | OXR1 | 170512    |              | OXQX  |
| 170404    | 848486003333 | OVGN  | 170416    |              | OVWN  | 170502    | 7/1          | OXR2 | 170512    | _            | 11A6  |
| 170404    |              | OVP6  | 170416    |              | OX29  | 1705CB    | 848486003487 | OR78 | 170513    | 848486003562 | OXQH  |
| 170404    |              | OVP5  | 110417    | 848486003449 | OR6Y  | 170503    |              | OR7A | 170513    |              | OXQG  |
| 170404    |              | OYBX  | 170417    |              | IONW  | 170503    |              | OXR4 | 170513    |              | OXQJ  |
| 170404    |              | OYBW  | 170417    |              | IONV  | 170504    | 848486003494 | OVL1 | 170513    |              | 10MR  |
| 170406    | 848486003357 | IONY  | 110418    | 848486003456 | OWC2  | 170504    |              | OVL2 | 170513    |              | lomv  |
| 170407    | 848486003364 | IONQ  |           | **           |       | 170504    |              | OX2C | 170513    |              | lomw  |
| 170407    |              | IONN  |           |              |       | 170504    | (I           | OX2B | 170514    | 848486003579 | 11AO  |
| 170408    | 848486003371 | 10N5  | 7         |              |       | 170506    | 848486003517 | OVIG | 170515    | 848486003586 | OPGM  |
| 170412    | 848486003395 | OVN1  | 7         |              |       | 170506    |              | OVIE | 170515    |              | OWC7  |
| 170412    |              | 1076  |           |              |       | 170507    | 848486003524 | OVJ3 | 170517    | 848486003609 | OBBQ  |
| 110413    | 848486003401 | OYBQ  |           |              |       | 170507    | 1.           | 1074 | 170517    |              | OBBR  |
| 170413    |              | 1OPE  |           |              |       | 170507    |              | IOMH | 170517    |              | 1077  |
| 110414    | 848486003418 | OVP7  |           |              |       | 170511    | 848486003548 | OWBW | 170518    | 848486003616 | 119X  |
| 170414    |              | OVP8  |           |              |       | 170511    |              | OWBX |           |              |       |
| 170414    |              | OYCO  |           |              |       |           | ×            |      | _         |              |       |
| 170414    |              | OYBY  |           |              |       |           |              |      |           |              |       |
| 170414    |              | 0YC2  |           |              |       |           |              |      |           |              |       |
| 170414    |              | OYC1  |           |              |       |           |              |      |           |              |       |