

Appendix A - List of Affected Part and Lot Numbers

<b>Part ID</b>	<b>Product Description</b>	<b>Lot ID</b>
1895	LNCS TC-I, 1/BOX, MASIMO	17J09, 17N06, 18BAA, 18CYG, 18ENJ, 18FAG, 18H3N, 18K47, 19DVR, 19F43, 19GCV, 19GSX, 19K42, 19K4V, 19KAM, 19NDD, 20C74, 20G8F, 20KGW, 20KQS, 20MJX, 21AGX, 21AXQ, 21BVK, 21EXD, 21EYU, 22E72, 22E91, 22GTT, E20H1G
2503	M-LNCS TC-I, 1/BOX, MASIMO	17HAX, 17N09, 19D84, 20FMM, 21EMP, 22DGZ
4053	RD Set TC-I, TipClip Ear Sensor 3ft 1/bx	17FAQ, 17KBP, 18E04, 18JPH, 18K49, 18KST, 18M03, 19D87, 19EAN, 19F47, 19GCW, 19HTV, 19KPZ, 19NRL, 20FUR, 20G2S, 20HFU, 20KMY, 20KUE, 20NGC, 21CTU, 21E09, 21EYT, 21FUG, 21G2S, 21JDD, 21MAT, 22APR, 22D18, 22DRN, 22FHY, 22FYS, 22G1W, 22JHE, 22JZX, E20H1H, E21DYW